



LOADING INSTRUCTIONS

1. Lift transparent cover and squeeze roll grips (**A**) allowing roll of labels to be placed into the machine.
2. Feed end of roll down into feed roller (**B**).
3. Pull operating lever (**C**) a few times to feed roll through the machine.
4. Hold the end of the roll towards the operating lever and close the platen assembly (**D**).
5. Followed by closing the bottom cover (**E**).